



Pending fixes for 0.0.2:
 1) 4-pin power on PCB is NOT CONNECTED!
 2) Pull-up resistors for I2C
 3) 1uF cap on Vref_out
 4) Grounding the AI pin causes overheating?